

Retracement of North Boundary of T. 23 S., R. 10 W.

CHAINS

79.98

Intersect the C. C. of secs. 3 and 4 heretofore described.

August. 30, 1906.

At the C. C. of secs. 3 and 4.

Thence I run

East, on a blank line along the N. bdy. of sec. 3.

Over mountainous land through heavy timber and dense brush.

2.81

Intersect the $\frac{1}{4}$ sec. cor. on S. bdy. of sec. 34 heretofore described.

10.85

Branch, 3 lks. wide, course NE.

19.00

Bed of gulch, course NW. and ascend.

39.72

My line falls 59 lks. S. of the old $\frac{1}{4}$ sec. cor. established under Contract No. 292. I destroy all evidence of this $\frac{1}{4}$ sec. cor.

41.50

Summit of ridge, 500 ft. above gulch, bears NE. and SW. Descend.

42.15

My line falls 64 lks. S. of the cor. of secs. 34 & 35, T. 22 S., R. 10 W. which is a stone, marked and witnessed as described by the Surveyor General.

The true bearing of this line is therefore N.89°04'E.

Thence, from the cor. of secs. 34 and 35, I run

East, on a blank line along the N. bdy. of sec. 3.

70.75

Branch, 3 lks. wide, 100 ft. below ridge, course N.

79.75

Intersect the line bet. secs. 2 and 3, 61 lks. S. of the C. C.

The true bearing of this line is therefore N.89°04'E.

Land, mountainous.

Soil, 3rd rate.

Timber, fir, hemlock, alder and scattering cedar.

Undergrowth, fir, hemlock, vine maple, salal, huckleberry and Oregon grape.

Land, mountainous, heavily timbered or covered with dense undergrowth, 78.30 chs.

August 18, 1906.