

## SUB-DIVISIONS OF T. 22 S., R. 12 W. W.M.

CHAINS

corner to Sections 22, 23, 26 and 27, from which

A Cedar, 20 ins. diam., bears N.37°E., 46 lks. dist.

A Cedar, 10 ins. diam., bears S.89°E., 117 lks. dist.

A Cedar, 10 ins. diam., bears S.20°W., 100 lks. dist.

A Cedar, 20 ins. diam., bears N.50°W., 95 lks. dist.

Land, broken mountainous, 3rd rate.

Timber, chiefly Fir and Cedar.

Undergrowth, same.

East on Random line between Sections 23 and 26.

Va. 18°East.

40.00 Set temp. Quarter Section corner

80.15 Intersect 28 lks. South of corner.

South 89°48'West on true line between Sections 23 and 26.

Va. 18°E.

1.75 A creek 20 lks. wide course N.20°W.

22.20 A creek 2 lks. wide course N.

33.00 Top of ridge course NW and SE.

40.07 Set Maple post 40 ins. long, 5 ins. diam., 20 ins. in  
ground for the Quarter Section corner between

Sections 23 and 26, from which

An Alder, 16 ins. diam., bears North, 24 lks. dist.

A Cedar, 60 ins. diam., bears S.89°W., 65 lks. dist.

48.00 A creek 2 lks. wide course W.

52.23 A creek 5 lks. wide course N.

80.15 To Section corner.

Land, mountainous 3rd rate.

Timber, same as former line.

Underbrush, same and Vinemaple.

June 10th, 1879.

The lands of this section are principally rough, 3rd rate, excepting a narrow strip extending along the meanderings of Wind Creek. Mr. Richards has located near the middle of the section and there is another house near the N. Boundary. In my judgment no lands adjoining this section unsurveyed are worthy of attention.