

## RETRACEMENTS OF EAST BDY. OF T. 22 S. R 12 W. W.M.

CHAINS

but bearing trees in position, I run

South, on a random line, on E. boundary of Sec. 24.

39.78 I close 93½ lks. E. of the old ¼ Sec. cor. which is nearly destroyed, cor. missing but bearing trees in position.

79.36 I close 187 lks. E. of the old cor. of Secs. 24 and 25 already described.

The true bearing of this mile is therefore N. 21° E.

May 2, 1880.

At the cor. of Secs. 24 and 25 on the E. boundary of the township, thence I run N. 1° 21' E., on a true line on E. boundary of Secs. 24. Descend general N. slope thru heavy timber and dense undergrowth.

8.50 Spring branch, 2 lks. wide, course E.

25.50 Spur, 150 ft. high, slopes NE.

28.90 Spring branch, 2 lks. wide, course E.

36.51 Spur, 300 ft. high, bears NE, SW.

Descend N. slope to creek.

39.43 Creek, 3 lks. wide, course NE., 200 ft. below spur.

39.58 The old ¼ Sec. cor. I destroy all trace of this old ¼ Sec. cor. and reestablish it at the same point, as follows.

Set a sandstone, 12x10x8 ins., 8 ins. in the ground for ¼ sec. cor. marked ¼ on W face: from which

A Spruce, 12 ins. diam., bears S. 80° W., 40 lks. dist., marked ¼ S 24 B T.

A Hemlock, 24 ins. diam., bears N. 73° 30' W., 49 lks. dist., marked ¼ S 24 B T.

52.27 Intersect the old decayed stump of closing cor. of Secs. 18 and 19 with old bearing trees - the stump has fallen to the ground and the marks are no longer visible on witness trees.

I destroy all trace of this old cor. and reestablish at the same point as follows: