

-3-  
County Surveyor's Record, Douglas County, Oregon

2129

West Bdy. of T. 23 S., R. 1 W. As surveyed by  
Henry L. Chandler, Deputy Surveyor, under Contract No. 619  
Dated June 5, 1893

CHAINS	<p>As I am directed to run the E. boundary of T. 23 S., R. 1 W. South an equal distance to the W boundary, I begin at the SW cor. of the township, old post decayed, set new post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. to Tps. 23 and 24 S., Rgs. 1 and 2 West, marked T 23 S S 31 on NE., R. 1 W S 6 on SE., T 24 S S 1 on SW., R 2 W S 36 on NW faces with 6 notches on each edge, from which old bearing trees</p> <p style="padding-left: 40px;">A hemlock, 6 ins. diam., bears N.41*E., 9 lks. dist. Marked T 23 S R 1 W S 31 B T</p> <p style="padding-left: 40px;">A red fir, 36 ins. diam., bears S.58*E., 32 lks. dist. Marked T 24 S R 1 W S 6 B T</p> <p style="padding-left: 40px;">A hemlock, 30 ins. diam., bears S.38*W., 30 lks. dist. Marked T 24 S R 2 W S 1 B T</p> <p style="padding-left: 40px;">A white fir, 30 ins. diam., bears N.68*W., 33 lks. dist. Marked T 23 S R 2 W S 36 B T</p> <p>Thence I run</p> <p>North on a blank line on the range line between ranges 1 and 2 West</p> <p style="text-align: right;">Va. 18½*E</p> <p>At 40.00 I am unable to find the ¼ sec. cor. and at 73.40 chs. I intersect the established cor. for secs. 25, 36 30 and 31. This being out of limits. I again begin at the SW cor. of the Tp. and reestablish the line as follows</p> <p>N on W boundary of sec. 31</p> <p style="text-align: right;">Va. 18½*E</p> <p>Descending through timber</p> <p>3.00 Creek, 1 lk. wide, course NE</p> <p>8.50 Creek, 2 lks. wide, course NE</p> <p>11.27 Creek, 1 lk. wide course SE <span style="float: right;">-150</span></p> <p>Ascend</p> <p>16.00 Top of spur, course E <span style="float: right;">+100</span></p> <p>Descend</p>
--------	---