

Subdivisions of T. 23 S., R. 4 W.

CHAINS

Land, mountainous
 Heavily timbered, or covered with dense undergrowth
 40.80 chs.

July 18, 1897

General Description

This fractional township is extremely rough and mountainous. The soil is unfit for agricultural purposes, being generally rocky; it is covered with a dense undergrowth of vine-maple, mountain-balm, ocean-spray, hazel, and salal berry.

There is some valuable timber in section 35, but difficult of access; it is principally fir, hemlock, and cedar.

The township, in this part, is well watered by numerous springs and clear mountain streams.

Carl S. Nicklin,
 U. S. Deputy Surveyor.

July 18, 1897

Retracements of T. 23 S., R. 4 W.

Same Deputy and Contract

To locate the witness cor. bet. secs. 34 and 35, I begin at the cor. of secs. 26 and 27, 34 and 35, which is a post, 4 ins. sq., marked and witnessed as described by the surveyor general; thence, I run

South, on a blank line, bet. secs. 34 & 35

39.65 To a point, 5 lks. E of the $\frac{1}{4}$ sec. cor., which is a post, 4 ins. sq. 20 ins. above ground, marked and witnessed as described by the surveyor general

61.73 To a point, 10 lks. E of the witness cor., bet. secs. 34 and 35, which is a post, 20 ins. above ground marked and witnessed as described by the surveyor general

Therefore, this line bears S.0°W