

- 5 -

Subdivisions of T. 23 S., R. 9 W. W.M.
 as surveyed by W.H. Byars, Deputy Surveyor under
 Contract No. 279, dated March 5, 1878.

CHAINS

N. on random line between Sections 5 and 6.

Va. 19°E.

40.00 Set temp. $\frac{1}{4}$ Sec. corner

80.23 Intersect Township line at corner.

South on true line between Sections 5 and 6.

25.00 Steep bluff, 50 feet high.

40.23 Set Fir post 4 ft. long, $\frac{1}{4}$ ins. diam., 20 ins. in
 ground for $\frac{1}{4}$ Sec. corner, from which,

A Fir, 48 ins. diam., bears N.65°E. 46 lks. dist.

A Fir, 48 ins. diam., bears S.80°W 36 lks. dist.

54.00 Creek, 3 lks. wide, course SW.

75.00 Creek, 1 lks. wide, course N.10°W.

80.23 To Section corner.

Land broken, hilly, 3rd rate.

Timber principally burned.

The lands of this township are valuable for the
 timber alone, found growing upon the them, with the
 exception of a small or narrow bottom along the creek
 and a few benches found upon the mountain-side.

Claims, however, are located all along the
 valley, and these settlers have assisted very mater-
 ially in the execution of this work.