

- 36 -

Subdivisions of T. 23 S., R. 9 W., W.M.  
same Deputy and Contract.

CHAINS

43.05 The cor. of secs. 29 and 32

Land mountainous

Soil, gravelly; 3rd rate.

Timber, Fir, Hemlock, Cedar, Maple, Dogwood.

Undergrowth, dense, Huckleberry, Vine-maple, salal berry.

Mountainous and heavily timbered land and land covered by  
dense undergrowth.

43.05 and 2.40 chs.

August 31, 1898.

---

As sec. 32 does not close within limits, I re-measure  
it's West boundary. I begin at the cor of secs. 31  
and 30 and run

South, bet. secs. 31 and 32.

38.85 Quarter section corner bears West 85 lks., it is a  
maple post 5 ins. sq. 30 ins. high, badly decayed,  
marked and witnessed as described by the surveyor  
general.

78.10 The cor. of secs. 31 and 32 on S. bdy. of tp. bears  
152 lks. West; it is a Fir post, 5 ins. sq., 24 ins.  
high, much decayed, marked and witnessed as described  
by the surveyor general.

September 1st, 1898.

---

NE. cor of secs. 18, which being gone, I set a Hemlock  
post, 3 ft. long, 4 ins. sq., 24 ft. in the ground  
for cor. of secs. 7, 8, 17 and 18. marked and witness-  
ed as described by the surveyor general. Thence I  
run on a true line N. 0° 4' W. bet. secs. 7 and 17.

Ascending a mountain slope, heavily timbered, large fir  
and hemlock.

4.00 Top of a ridge, bears E. and W., along a bench covered  
by a dense undergrowth of small firs, hemlock and  
vine-maple; begin a gradual descent of N. slope.