

Meanders of Loon Lake in Secs. 1, 2, 11 & 12.

CHAINS

In section 2.

Beginning at the Meander or Witness corner between secs.
2 and 11, I run,

Va. 19thE.

N.16 th W	16.50	Low & rocky.
N.70 th W	16.00	Steep & rocky.
N.20 th W	12.00	Steep & rocky.
North	4.00	Steep & rocky.
N.45 th E.	6.00	Broken & rocky.
East	8.00	Broken & rocky.
S.45 th E.	1.50	Across outlet of lake, Mill creek.
N.15 th W	3.00	Low marshy.
East	3.00	Low marshy.
South	3.50	Steep rocky shores.
S.80 th E.	20.90	Steep rocky shores.

Land of little value except for
timbers and milling site at outlet
of lake.

In sec. 1.

Beginning at Meander or Witness corner on North side of
lake between secs. 1 and 2, I run,

Va. 19thE.

S.80 th E	8.00	Steep rocky.
S.12 th E	23.50	Steep rocky.
S.12 th W	6.00	Steep rocky.

Lands in this section adjoining lake
are of little or no value.

June 6, 1879.

GENERAL DESCRIPTION

The quality of the lands in this township are varied. The
lands along Lake creek are rich bottom varying in width
from 5 to 60 chains. Some bench lands are found on
the hills back from the creek which are good and are
susceptible of cultivation. A vast amount however is
broken mountainous, 3rd rate. Timbers burned off.