

## Resurvey of the line bet. secs. 14 and 15, T. 23 S., R. 10 W.

 CHAINS  
79.66

The cor. of secs. 14 and 23.

Land, mountainous.

Soil, 3rd rate.

Timber, fir and hemlock.

Undergrowth, fir, hemlock, vine maple and salal.

Land, mountainous, heavily timbered or covered with dense undergrowth, 79.66 chs.

July 28, 1906.

 Retracement of the line bet. secs. 11 and 14, T. 23 S., R. 10 W.  
At the NW cor. of sec. 14.

Thence I run

S.89°33'E., on a blank line bet. secs. 11 and 14.

Through old burn.

2.50 Enter green timber, bears NW and SE.

11.00 Enter bottom, bears N and S.

12.40 Salander Creek, 15 lks. wide, course NE.

13.50 Leave bottom and ascend.

29.00 Bed of dry gulch, 25 ft. deep, course NW.

 39.91 Intersect the  $\frac{1}{4}$  sec. cor., which is a yew post, firmly set, marked and witnessed as described by the Surveyor General.

 The B. T's. being dead and marks on post illegible, I remark the post,  $\frac{1}{4}$  S 11 on N., and 14 on S face, from which

 A fir, 8 ins. diam., bears N.30°W., 13 lks. dist., marked  $\frac{1}{4}$  S 11 B T.

 A fir, 8 ins. diam., bears S.17°W., 14 lks. dist., marked  $\frac{1}{4}$  S 14 B T.

47.50 Top of ascent on S slope of mountain, 450 ft. above Salander Creek, and descend 400 ft. to

78.85 Intersect the cor. of secs. 11, 12, 13 and 14.

The old post being gone, by reference to the B. T's I relocate the point where it stood where I

Set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 11, 12, 13 and 14, marked