

Supplemental Notes of Subdivisions of T. 24 S., R. 4 W.  
Corrections

CHAINS

but the bearing trees remaining, I reestablish line bet. secs. 10 & 15; the post for cor. of secs. 9, 10, 15 & 16 being gone

Line bet. secs. 11 & 10

The post for cor. of secs. 2, 3, 10 & 11 being gone but bearing trees remaining I reestablish

Line bet. secs. 3 & 4

All marks on old post and bearing trees referring to the new work were effaced or corrected

Line bet. secs. 4 & 5

The post for cor. of secs. 4, 5, 32 & 33 being gone but the bearing trees remaining I reestablish

Line bet. secs. 10 & 11

If I have written S.0\*9'W., on true line bet. secs. 10 & 11 please to correct to S.0\*7'W., on true line bet. secs. 10 & 11

Oscar F. Thiel  
U.S. Deputy Surveyor

## Supplemental Notes of Subdivisions of T. 24 S., R. 4 W.

At temp.  $\frac{1}{4}$  sec. cor. bet. secs. 1 & 2 which line reversed agrees with the line run last year

Thence I run

N.0\*1'W., on a Random line bet. secs. 1 & 2

Ascend over rough, stony ground, sloping SW

39.70 Intersect North boundary of township, 28 lks. W. of cor. of secs. 1, 2, 35 & 36 which is a basalt stone 8x8x5 ins. above ground marked and witnessed as described by Carl S. Nicklin, U.S. Deputy Surveyor, under Contract No. 664 July 16, 1897 and filed in the office of Surveyor General

Thence I run

S.0\*11'W., on true line bet. secs. 1 & 2

Descend over rough stony ground sloping W covered with heavy Fir Timber

8.50 The slope changes to the SW still descending; burnt timber