

Supplemental Notes of Subdivisions of T. 24 S., R. 4 W.

- CHAINS is intermixed with the green timber
- 39.70 Set a basalt stone 12x10x6 ins., 8 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W face from which
- A Laurel, 7 ins. diam., bears S.46*E., 57 lks. dist.,
Marked $\frac{1}{4}$ S B T
- A Laurel, 8 ins. diam., bears S.78*W., 21 lks. dist.,
Marked $\frac{1}{4}$ S B T
- I destroyed the marks on the former bearing trees
This cor. stands 100 ft. below sec. cor.
Keep on descending
- 46.10 A Branch 10 lks. wide, course West about 100 ft. below $\frac{1}{4}$ sec. cor.
- Begin steep ascent of North slope
- 54.60 Top of Mountain, bears E & W 350 ft. above branch
- 61.50 Begin steep descent of South slope of Mountain
- 73.70 Descent moderates at this point, 500 ft. below top of mountain
- 79.70 The cor. of secs. 1, 2, 11 & 12
- Land Mountainous
Soil, stony, 4th. rate
Timber, Fir, Cedar, Chinquapin, Laurel
Mountainous or heavily timbered land, 79.70 chs.
- September 14, 1897
-
- Retracements of East Boundary of Sec. 1 T. 24 S., R. 4 W.
-
- At the closing cor. of secs. 1 & 12
Thence I run
North, on East Boundary of sec. 1 bet. secs. 1 & 6
Ascend rough SW slope of mountain, covered with heavy
Fir Timber, which has been burnt in patches
Between 30 and 40 chs. I made a diligent search for the
 $\frac{1}{4}$ sec. cor. but failed to find any traces of the same
or the bearing trees belonging to it
- 75.00 Intersect South Boundary of T. 23 S., R 3 W 85 lks. E of its
SW cor. which is a sandstone 12x8x6 ins. above ground