

Supplemental Notes of Subdivisions of T. 24 S., R. 4 W.  
Retracement of East Boundary of Sec. 1, T. 24 S., R. 4 W.

CHAINS

marked and witnessed as described by the Surveyor General  
I chained 3.58 chs. East from said cor. but fires have  
repeatedly been through here and no sign of post or its  
small bearing trees remain. The fact is that through  
the whole 4 miles of this township line I retraced, there  
is no  $\frac{1}{4}$  sec. cor. or any blazes to be found

Land Mountainous

Soil, stony, 4th. rate

Timber, Fir, Cedar, Alder, Chinquapin, Laurel

Mountainous or heavily timbered land. 75.00 chs.

September 15, 1897

Retracement of the North Boundary of Sec. 3., T. 24 S., R. 4 W.

At the cor. of secs. 2, 3 & 34

Thence I run

S.69°58'W., on true line bet. secs. 3 & 34

Over rough ground, covered with heavily Fir Timber and a  
dense undergrowth of Hazels and small Fir Timber

.50 Leave Top of Ridge bears N & S; begin to descend

9.50 A Dry Gulch course N. 80 ft. below ridge

Ascend again

24.50 Top of ridge bears NW, SE. 50 ft. above gulch

Begin to descend

39.91  $\frac{1}{4}$  sec. cor. which is a Hemlock Post, 3 ins. sq., 24 ins.  
above ground, marked and witnessed as described by the  
Surveyor General

58.40 A Road bears N & S

65.00 A Branch 15 lks. wide, course N.30°W., 150 ft. below  $\frac{1}{4}$  sec.  
cor.

75.40 A Stream 2 lks. wide, course NE

77.68 The cor. of secs. 3, 4, 33 & 34

Clouds prevented the taking of latitude

Land Mountainous

Soil, gravelly, 3rd. rate

Timber, Fir, Cedar, Hemlock, Maple

Mountainous or heavily timbered land. 77.68 chs.