

Supplemental Notes of Subdivisions of T. 24 S., R. 4 W.  
Retracement of the line bet. secs. 5 & 6, T. 24 S., R. 4 W.

## CHAINS

At the cor. of secs. 5, 6, 7 & 8 which is an Alder Post  
4 ins. sq., 24 ins. above ground set October 7, 1885 by  
the county surveyor marked and witnessed as described by  
surveyor general

Thence I run

N.1\*0'E., on line bet. secs. 5 & 6

Ascend West slope of mountain covered with Oaks and Firs

2.25 A Dry Stream course SW

19.00 A Dry Stream course SE

39.75  $\frac{1}{4}$  Sec. cor. bears E. 21 lks.

41.80 Top of dividing ridge between the waters flowing in Elk  
Creek and Calapooya Creek bears NW and SE

Descend

80.03 Intersect North Boundary of township, 70 lks. West of cor.  
of secs. 5, 6, 31 & 32 which is a badly decayed Alder Post  
3 ins. sq., 3 ft. above ground marked and witnessed as  
described by the Surveyor General

Land South half hilly, North half Mountainous

Soil, South half loamy <sup>and</sup> rocky, 3rd. rate

North half gravelly stoney, 4th. rate

Timber, Fir, Oak, Laurel, Maple, Alder

Mountainous or heavily timbered land. 80.03 chs.

Clouds prevented observation at noon

September 17, 1897

The North Boundaries of secs. 5 & 6 equal 82.40+77.29=  
159.69 chs.

The South Boundaries of same secs. equal 80.72+79.76=  
160.48 chs. making a difference of 79 lks. for 2 miles

Correction of Subdivisions of T. 24 S., R. 4 West

Line bet. secs. 1 & 2

N.0\*1'W., on a Random line bet. secs. 1 & 2, the same as  
it stands on my plat

Oscar F. Thiel

U.S. Deputy Surveyor