

## Subdivisions of T. 24 S., R. 6 W.

CHAINS		
	A fir, 20 ins. diam., bears N.23*E., 37 lks. dist. Marked T 24 S R 6 W S 30 B T	
	A fir, 14 ins. diam., bears S.3*E., 36 lks. dist. Marked T 24 S R 6 W S 31 B T	
	A fir, 6 ins. diam., bears S.52 $\frac{1}{2}$ *W., 45 lks. dist. Marked T 24 S R 7 W S 36 B T	
	A fir, 14 ins. diam., bears N.50*W., 34 lks. dist. Marked T 24 S R 7 W S 25 B T	
	Thence I run N.89*48'E on true line bet. secs. 30 and 31 Va. 20*30'E	
20.50	Canyon creek, 10 lks. wide, course N.50*E.	-900
27.00	Top of spur, course N & S	+100
28.30	Stream 3 lks. wide, course N.10*W.	-40
29.07	Spring runs NW	+70
40.00	Top of spur, course N & S	+246
41.57	Set yew post, 4 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face, from which A fir, 55 ins. diam., bears N.66*45'W., 47 lks. dist. Marked $\frac{1}{4}$ S B T A cedar, 30 ins. diam., bears S.58*30'E., 133 lks. dist. Marked $\frac{1}{4}$ S B T	-23
43.37	Stream 3 lks. wide, course N.30*W	-65
46.50	W edge of bench land	+45
52.97	Spring, runs NW	00
62.35	Summit of ridge N.10*E. & S.10*W	+107
81.57	To cor. to secs. 29, 30, 31 & 32 The West half of this mile is very steep and rocky, mountainous. Soil, very poor, 4th rate Timber, nearly all dead fir, cedar, laurel, maple Undergrowth, hazel, arrowwood, fir, fern, briar. The east half has some good soil, 1st and 2nd rates and	-603