

Subdivisions of T. 24 S., R. 6 W.

CHAINS		
71.00	Stream 5 lks. wide, course SW	-300
72.00	Leave canyon	+42
78.00	Stream 1 link wide, course S.75*W.	+37
80.00	Enter burn	
82.00	The cor. to secs. 17, 18, 19 & 20	
	The West 25 chs. of this mile is very rough and rocky.	
	Soil, 4th rate	
	Timber, fir and cedar, not very good.	
	Dense undergrowth of fir, cedar, hazel, arrowwood, & briars	
	The next 25 and the East 10 chs. have good soil, 1st & 2nd	
	rate. The balance is very rough and rocky, soil, 4th	
	rate.	
	Heavily timbered with fir, cedar and laurel.	
	Dense undergrowth of fir, hazel, arrowwood, briars & salal	
	Mountainous, 82.00 chs.	
	74.60 chs., timber & brush	
	Aug. 19, 1891	
	N.89*30'E. on random line between secs. 17 & 20	
	Va. 20*52'E.	
40.00	Set temporary $\frac{1}{4}$ sec. cor.	
79.78	Intersect N & S line 27 lks. North of cor. to secs. 16,	
	17, 20 & 21. Post gone. Reestablished same by setting	
	fir post 4 ft. long, 4 ins. sq. 24 ins. in the ground,	
	marked T 24 S S 16 on NE, R 6 W S 21 on SE, S 20 on SW	
	and S 17 on NW faces, with 3 notches on the South and	
	4 notches on the E edges, from which	
	A maple, 14 ins. diam., bears N.50*E., 79 lks. dist.	
	Marked T 24 S R 6 W S 16 B T	
	A laurel, 10 ins. diam., bears S.15 $\frac{1}{2}$ *E., 39 lks.	
	dist. Marked T 24 S R 6 W S 21 B T	
	A laurel, 8 ins. diam., bears S.18*W., 79 lks. dist.	
	Marked T 24 S R 6 W S 20 B T	