

Correction and Explanation of the Survey of T. 24 S. R. 7 W.

CHAINS

Line bet. secs. 26 and 27.

Post plainly marked  $\frac{1}{4}$  S.

June 16, 1896.

South Bdy. of Tp., cor. to secs. 3 and 4, T 25 S R 7 W.

Here on careful examination, I find my notes correct in every particular.

June 16, 1896.

At the old cor. to Tps. 24 and 25 S R 6 and 7 W., I destroyed all marks referring to Tps. 24 and 25 S R 7 W.

June 16, 1896.

Line bet. secs. 25 and 36.

After setting C C for secs. 25 and 36, I destroyed all marks referring to these sections on old cor., also bet. secs. 24 and 25, and bet. secs. 23 and 24, and at cor. to secs. 14, 15, 22 and 23.

The east boundary of Tp., and the line North from the cor. to secs. 35 and 36 are over a mountainous country, covered by heavy timber with a dense growth of underbrush and much fallen timber, which renders perfect accuracy in chaining impossible.

Bet. secs. 11 and 14, at

71.56 I intersect witness cor. I did not fall north or south of cor.

Line bet. secs. 15 and 22.

I destroy the  $\frac{1}{4}$  sec. cor. and at

37.35 which is in middle of the line, I set post, 4 ins. sq., 4 ft. long, 24 ins. in the ground for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S on N., from which