

Resurvey of West Boundary T. 24 S., R. 8 W.

CHAINS

80.00

Secs. and Tps. East of this line.

Set a sandstone 20 x 10 x 6 ins., 15 ins. in the ground for cor. to Tps. 23 & 24 S., R. 8 W., marked with 6 notches on North, South and East edges, from which

A Fir, 18 ins. diam., bears N.14°E., 53 lks. dist., marked T 23 S R 8 W S 31 - B T.

A Fir, 18 ins. diam., bears S.22°E., 71 lks. dist., marked T 24 S R 8 W S 6 - B T.

A Fir, 12 ins. diam., bears S.40°W., 10 lks. dist., marked T 23 and 24 S R 8 W B T.

Land, broken.

Soil, 2nd rate.

Heavily timbered with Fir and Hemlock. 80.00 chs.

Dense undergrowth of vinemaple, hazel and salal.

80.00 chs.

May 21st, 1894.

The random line which I have previously run West along the North boundary of T 24 S R 8 W falls 20 lks. North of the above established cor. to Tps. 23 and 24 S R 8 W and the length of the said random line is 5 miles, 59 chs. and 33 lks. as previously shown.

The course of the true line will be N.69°59'E., and the correction will be 3 lks. South per mile.

Subdivisions of T. 24 S., R. 8 W.
Same Deputy and Contract.
(CHANDLER 1893)

From the Township cor. I run North on East Boundary of Sec. 36.

Va. 19°10'E.

And at 40.09 chs. I find the $\frac{1}{4}$ sec. cor. 2 lks. East