

Subdivisions of T. 24 S., R. 9 W., W. M.

CHAINS

63.00 Lake Creek 150 lks. wide, course NW.

78.04 To sec. cor.

Land, 2nd rate.

Timber, chiefly young fir. Underbrush, same as last line.

May 9, 1879.

The lands surveyed in this township cover all the lands valuable or fit for agriculture or timbers.

Those not surveyed are generally high, mountainous, and at this time are of no value.

The valley along the creek is very good soil, varying in width from 2.00 to 50.00 chains on the main creek with several small valleys on the smaller tributaries.

Resurvey of the East Boundary of T. 24 S., R. 10 W., as surveyed by Elmer O. Worrick and Alonzo Gesner, Deputy Surveyors, under Contract No. 659, dated May 21, 1896.

From the cor. to Tps. 23 and 24 S., Rs. 9 and 10 W.,

I run South.

Var. 20*E.

Ascend.

0.30 Steep rocky spurs.

3.00 Top of rocky spurs.

Sloping NW.

Descend.

5.00 Creek 6 lks. wide, course NW.

10.10 Same stream 6 lks. wide, course N.10*E.

Pass over spur.

39.94 The $\frac{1}{4}$ sec. cor. The post and bearing trees agreeing

with notes of the original survey, continued south

from this cor.

48.00 Creek 2 lks. wide, course E.

56.00 Creek 2 lks. wide, course E.

64.05 Creek 3 lks. wide, course E.

Pass over spur.

77.98 To a point 105 lks. E. of the cor. to secs. 1, 12, 6 & 7.

Land, mountainous; soil, 2nd and 3rd rate.

77.98 chs.