

Resurvey of South Boundary of T. 24 S., R. 9 W.

CHAINS

- 39.34 My line falls 41 lks. North of the $\frac{1}{2}$ sec. cor. which is a post, firmly set, marked and witnessed as described by the Surveyor General.
- 78.66 My line falls 34 lks. N. of the established cor. of secs. 31 and 32, which is a post, firmly set, marked and witnessed as described by the Surveyor General.
- August 24, 1905.
-
- From the cor. of secs. 31 and 32.
Thence I run
West, on a blank line on S. bdy. of sec. 31.
- 23.60 At this point I make careful search for the closing corner of secs. 5 and 6, but can find no evidence of it.
- 39.28 My line falls 64 lks. North of the $\frac{1}{2}$ sec. cor. which is a vine maple, 5 ins. dia., marked and witnessed as described by the Surveyor General.
- 80.89 Intersect the range line, 35 lks. N. of the established cor. of Tps. 24 and 25 S., Rs. 9 and 10 W., which is a post firmly set, marked and witnessed as described by the Surveyor General.
- August 24, 1905
-
- The falling answers to a correction of 35 lks. per mile. or $0^{\circ}15'N.$ counting from the SW. cor. of the TP:
Therefore, I resurvey the South Boundary of these secs. as follows:
From the corner of Tps. 24 and 25 S., Rs. 9 and 10 W.
Thence I run.
 $N.89^{\circ}45'E.$, on true S. bdy. of Sec. 31.
Over mountainous land, through heavy timber and dense undergrowth.
- 1.60 Branch, 1 lk. wide, 20 ft. below Tp. cor.; course $S.70^{\circ}E.$
Thence along mountainside sloping S.