

## County Surveyor's Record, Douglas County, Oregon

Retracement of Subdivision lines of Township 24 S., R. 9 W.  
As surveyed by Levi C. Walker, Deputy Surveyor, under  
special instructions, dated Aug. 23, 1905, independent of  
but in connection with his Contract No 763, dated  
June 20, 1905

## CHAINS

The boundaries of sec. 34 not closing within allowed limits,  
and having satisfied myself that my work is correct, to  
determine the error, I retrace E. bdy. of the sec. as  
follows:

At cor. of secs. 34 and 35 on S. bdy. of T. 24 S., R. 9 W.  
I find a fir tree 22 ins. dia., marked S. 34 T 24 S R  
9 W B T.

From this tree I measure S.88°E., 26 lks. and set a maple  
post 3 ft. long, 4 ins. sq., 24 ins. in the ground for  
cor. of secs. 34 and 35, marked

T 24 S S 35 on NE., and

R 9 W S 34 on NW. face, with 2 notches on E., and  
4 notches on W. edge.

This cor. stands where old blazed line from N. intersects  
old blazed lines from E. and W. I could find no other  
evidence of cor.

The cor. stands in a heavy windfall which I suppose has  
obliterated other evidence of cor.

I mark a new bearing tree as follows:

A fir, 48 ins. dia., bears N.67°E., 22 lks. dist.  
mkd. T 24 S R 9 W S 35 B T.

At the cor. of secs. 34 and 35.

Thence I run

North, between secs. 34 and 35.

Over mountainous land through heavy timber and dense under-  
growth.

34.40 Bear Camp Creek, 5 lks. wide; course W.

40.31  $\frac{1}{2}$  sec. cor. between secs. 34 and 35 which is a hemlock tree,  
10 ins. dia., marked and witnessed as described by the  
Surveyor General.

78.99 The cor. of secs. 26 and 35, which is a stump of a fir  
tree, 10 ins. dia., badly decayed, witnessed as  
described, by the Surveyor General.