

Retracement of Subdivision of T. 24 S., R. 9 W.

CHAINS

The trunk of tree lying on the ground is still marked as described by the Surveyor General, I destroy the same and obliterate all marks on bearing trees referring to secs. 27 and 34.

Set a fir post, 3 ft long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 26 and 35, marked

T 24 S S 26 on NE., and

R 9 W S 35 on SE. face, with 2 notches on E., and

1 notch on S. edge.

Land, mountainous.

Soil, 3rd rate.

Timber, fir and hemlock.

Undergrowth, rhododendron, Oregon grape, salal and huckle berry.

Land, mountainous, heavily timbered or covered with dense undergrowth, 78.99 chs.

The boundaries of sec. 22 not closing in limits, after retracing my own lines and finding them correct, in order to locate the error I proceed as follows:

At the cor. of secs. 22, 23, 26 and 27.

The old post being much decayed, I destroy it and at the same point,

Set a fir post, 3 ft long, 4 ins. sq., 24 ins. in the ground, for the cor. of secs. 23 and 26, marked

T 24 S S 23 on NE., and

R 9 W S 26 on SE face, with 2 notches on S. and E.

edges.

Thence I run

North, on a blank line between secs. 22 and 23.

Over mountainous land through heavy timber and dense undergrowth.

2.90 Branch, 1 lk. wide; course SW.

12.50 Top of ridge, bears NW. and SE.