

## Retracement of Subdivisions of T. 24 S., R. 9 W.

CHAINS

The true bearing of this line is therefore N.89°20'W.

Land, mountainous.

Soil; 2nd rate.

Timber, fir and hemlock.

Undergrowth, vine maple, rhododendron, salal and  
huckleberry.

Land, mountainous, heavily timbered or covered with  
dense undergrowth, 7706 chains.

September 26, 1905

Subdivision Lines of T. 24 S., R. 9 W.  
Same Deputy and Contract.

At the corner of secs. 3, 4, 33 and 34 on the south Bdy.  
of the Township, which is a fir post, 4 ins. square,  
firmly set, marked and witnessed as described by the  
Surveyor General.

I destroy all marks on post and bearing trees referring to  
secs. 3 and 4, T. 25 S., R. 9 W.

Thence I run

N.0°1'W., bet. secs. 33 and 34.

Descend over mountainous land through heavy timber and  
dense undergrowth.

- 2.04 A fir tree, 18 ins. dia., on line I mark with 2 notches on  
N. and S. sides.
- 16.75 A branch, 2 lks. wide, 400 ft. below sec. cor; course N.20°E.
- 40.00 Set a yew post, 3 ft. long, 4 ins. sq., 24 ins. in the  
ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S 33 on W., and 34 on E.  
face, from which