

## Subdivisions of T. 24 S., R. 9 W., W. M.

CHAINS

Mountainous or heavily timbered land, or land covered with dense undergrowth, 80.00 chs.

August 8, 1905

At the cor. of secs. 27, 28, 33 and 34.

Thence I run

East, on a random line between secs. 27 and 34.

40.00 Set temp.  $\frac{1}{2}$  sec. cor.

80.19 Intersect N. and S. line 1.18 chs. N. of cor. of secs. 26, 27, 34 and 35 which is a decayed stump, marked and witnessed as described by the Surveyor General.

This close, being in excess of the prescribed limits, I retrace my lines and find them correct.

I then return to the established cor. of secs. 26, 27, 34 and 35, and destroy marks on cor. referring to secs. 27 and 34 and at the point of intersection of my random line with the West line of sec. 26,

I set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for C. C. of secs. 27 and 34, marked C.C T 24 S R 9 W on W.,

S 27 on N., and

S 34 on S. face, with 1 groove on S. face; from which A fir, 20 ins. dia., bears S.38\*W., 50 lks. dis. mkd. T 24 S R 9 W S 34 B T .

A fir, 20 ins. dia., bears N.23\*W., 60 lks. dis. mkd. T 24 S R 9 W S 27 B T.

Thence I run

West, on a true line bet. secs. 27 and 34.