

Subdivisions of T. 25 S., R. 5 W.

CHAINS

General Description.

The SE. Corner of this Township is high, broken mountain, timbered with fir, oak, etc., with numerous deep ravines and is unsurveyed, it being unfit for settlement. There is also a range of hills along the North Boundary, principally timbered with oak. Soil 2d and 3d rate. The balance of the Township is principally level and rolling prairie. Soil 1st and good 2d rate, and is all settled. There are from 15 to 20 settlers in this Township.

Subdivisions of T. 25 S., R. 5 W.
As surveyed by W. H. Byars, Deputy Surveyor,
Under Contract No. 152, dated June 3d, 1871.

From the Post corner to Secs. 1, 2, 35 & 36, on the South Boundary of the Township, I run North bet. Secs. 35 & 36.

Variation by Burt's Improved Solar Compass. 19* East.

5.00	Enter Prairie, course E. & W.	+100
29.00	Top of Ridge, course NE. & SW.	+800
36.00	Water in Gulch, course W.	-00
40.00	Set $\frac{1}{4}$ Sec. Post, from which	+100
	A W. Oak, 5 ins. diam., bears N.40*W., 6 lks. dist.	
	A W. Oak, 5 ins. diam., bears S.40*E. 12 lks. dist.	
52.00	Top of Spur, W. slope, course E. & W.	+900
60.00	Enter Timber, course E. & W.	+700
80.00	Marked a Fir, 3 ins. diam. for the Cor. to Secs. 25, 26, 35 & 36.	-300

No other trees convenient for witness trees.

Land 2d and 3d rate.

Timber, 3d rate. Principally fir and oak.

Underbrush same and hazel.