

West Bdy. of T. 25 S., R. 6 W., T. M.

CHAINS

80.00 Set a Cedar post, 40 ins. long, 4 ins. dia., 1/3 in ground, for the cor. to secs. 1, 6, 7 and 12, from which

A Fir, 18 ins. dia., bears N.60°E., 5 lks. dis.
 A Fir, 36 ins. dia., bears S.2°E., 26 lks. dis.
 A Fir, 36 ins. dia., bears S.2°W., 18 lks. dis.
 A Fir, 16 ins. dia., bears N.40°W., 5 lks. dis.

Land, broken, rocky, mountainous, 3rd rate.
 Timber, principally destroyed by fire.

September 7, 1877.

The survey of the foregoing lines are made in order to inclose sec. 7, that Mr. W. C. Burk may locate and perfect his homestead or preemption title thereon. The West Bdy. of sec. 6 was not run because; 1st, the sec. was considered, or especially the W. half, of no value; 2nd, the line extended through such breaks and canyons, that it would be almost impossible to extend it and 3rd, a rain storm coming on at this time, compelled a temporary suspension of the work, which so scattered the employees that it was considered impracticable to run the line.

Subdivisions of T. 25 S., R. 6 W., W. M.
 as surveyed by Wm. H. Byars, Deputy Surveyor,
 under Contract 272, dated August 22, 1877

Beginning at the cor. to secs. 7, 12, 13 and 18, I run East, on random line bet. secs. 7 and 18.

Va. 18°E.

40.00 Set tem. $\frac{1}{4}$ sec. cor.

80.93 Intersect line, 150 lks. S. of cor. to secs. 7, 8, 17 and 18, which I established as per field notes furnished from the surveyor generals office; viz.

A Y. Oak, 10 ins. dia., bears S.15°E., 18 lks. dis.
 A Y. Oak, 7 ins. dia., bears S.47 $\frac{1}{2}$ °W., 13 lks. dis.