

Subdivisions of T. 25 S., R. 7 W.

CHAINS

N.0*2'W., on a Random line between Secs. 3 and 4.

Var. 20*E.

40.00 Set temp. $\frac{1}{2}$ sec. cor.

80.66 Intersect N. bdy. of Tp., 21 lks. E of cor. to Secs.
3 and 4.

Thence I run

S.11'E., on a True line between Secs. 3 and 4.

Ascend from cor. 150 ft. to

15.00 Summit of ridge, with trail, bears NE and SW.

40.66 Mark cross (x) 1 ft. long on a large rock at this
point for $\frac{1}{2}$ sec. cor., from which

A Cross (x) out in rock, bears N.10*E., 8 lks.
dist.

A Cross (x) out in rock, bears N.28*W., 210 lks.
dist.

No living tree within limits, pits or mound impractic-
able owing to the steep and stony condition of the
surface.

60.90 Point 600 ft. below trail where witness cor. should be,
which I fail to find or any trace thereof. Descend to

80.66 The cor. to Secs. 3, 4, 9 and 10.

Land, mountainous.

Soil, 4th rate for the first 40.46 chs., 3rd rate for
the last 40.00 chs.

No timber of value on the first 45.00 chs., good Fir
on the last 35.46 chs.

Undergrowth, Arrow-wood, Chinquapin, Fir and Hemlock.

Mountainous land, or land covered with dense under-
growth, 80.66 chs.

As the closing indicates an error, either in the
measurement of the S. bdy. of the Sec., or the align-
ment of the W. bdy. from the cor of Secs. 3, 4, ⑧
and 9,