

East Boundary of T. 25 S., R. 9 W.

CHAINS

Thence over level land

74.85 Intersect S. Bdy. of T. 24 S., R. 9 W. 23.54 chs. W. of the cor. of Tps. 24 & 25 S., Rs. 8 and 9 W. which is a post 4 ins. sq. 1 ft. above ground marked and witnessed as described by the surveyor general. I destroy all markings on old cor. pertaining to Tps. 25 S., Rs. 8 and 9 W. At point of intersection I set a fir post 8 ins. sq. 3 ft. long 24 ins. in the ground for closing cor. of Tp. 25 S., Rs. 8 and 9 W. marked C C T 25 S on the S., R 8 W S 6 on the E. and R 9 W S 1 on the W. faces with 6 grooves on the S., E., and W. faces from which

A fir, 36 ins. diam., bears S.30°E. 93 lks. dist.
marked T 25 S R 8 W S 6 B T

A fir, 40 ins. diam., bears S.61 3/4°W. 20 lks. dist.
marked T 25 S R 9 W S 1 B T

Land level and mountainous

Soil sandy loam, 1st and 2nd rate

Timber hemlock, fir and cedar

Undergrowth huckle berry, small fir and laurel

Mountainous and heavily timbered land 74.85 chs.

Oct. 9, 1902

Retracement of the S. Bdy. T. 25 S., R. 8 W.
As surveyed by Morris Wygant, Compassman for Zachariah
M. Derrick, U. S. Deputy Surveyor, Under Contract No.
779, dated Feb. 7, 1908

At the cor. of secs. 4, 5, 32 and 33, on the S. bdy. of Tp., previously described.

Thence I run

West, retracing bet. secs. 5 and 32.

39.40 Fall 3 lks. S. of the 1/4 sec. cor., which is a myrtle tree, badly decayed, marked and witnessed as described by the Surveyor General. I reestablish as follows: Destroy old 1/4 sec. cor. and at the exact point, I set a fir post 3 ft. long, 3 ins. sq., 24 ins. in the ground for 1/4 sec. cor., marked 1/4 S 32 on N. and 5 on