

Retracement-Reestablishment  
Portion of S. Bdy. of T. 26 S., R. 2 W.

CHAINS

Timber, fir, cedar and pine

Undergrowth, fir and laurel thickets

October 27, 1913.

October 28:

East, retracing the S. bdy. of sec. 33.

Descend along SE slope through heavy timber and dense undergrowth.

2.55 Stream 3 lks. wide, course SE

20.37 Stream, 3 lks. wide, course SE

40.27 Fall 12 lks. S. of the  $\frac{1}{4}$  sec. cor., which is a cedar post, 4 ins. sq. firmly set, marked and witnessed as described by the surveyor general.

The true course and distance of this line is N.89°50'E., 40.27 chs.

I continue my measurements

East, from the  $\frac{1}{4}$  sec. cor., counting distance from sec. cor.

42.40 Stream, 2 lks. wide, course S

47.47 Stream, 1 lk. wide, course S

51.54 Stream, 4 lks. wide, course SE

58.00 Foot of descent; ascend rocky irregular SW slope

68.00 October 28. Descend

71.80 Stream, 4 lks. wide, course SW., in deep canyon; ascend on steep slope

79.99 Fall 27 lks. S. of the cor. of secs. 3, 4, 33 and 34, which is a cedar post, badly decayed, witnessed by the NE and NW bearing trees as described by the surveyor general; all other traces of the cor. have disappeared. I destroy this cor. and re-establish it in the same place, as follows:

Set a cedar post, 3 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. of secs. 3, 4, 33 and 34, marked T 26 S S 34 on NE., R 2 W S 3 on SE, T 27 S S 4 on SW and S 33 on NW faces, with 3 notches on E and W edges; from which