

Subdivisions of T. 26 S., R. 3 W.

CHAINS	<p>A laurel, 8 ins. diam., bears S.65*W., 60 lks, dist.</p>	
80.84	<p>To sec. cor.</p> <p>Land, rough, broken, 3d rate.</p> <p>Timber, poor, principally oak grubbs and poison oak.</p>	-100
	<p>The cor. to secs. 3, 4, 9 and 10, was not standing.</p> <p>Established cor. as per field notes furnished excepting the witness tree in sec. 4, viz.</p> <p>A B. oak, 14 ins. diam., bears N.30*W., 30 lks. di st.</p> <p>Should read 20 lks. dist. instead.</p> <p style="text-align: right;">August 1, 1877.</p>	
	<p style="text-align: center;">Subdivisions of T. 26 S., R. 3 W. As surveyed by W. H. Byars, Deputy Surveyor Under contract No. 317, dated Jan. 20, 1879.</p>	
X	<p>From the cor. to secs. 1, 6, 7 and 12, on E bdy. of tp. said post was found rotted down., witness trees all standing, viz.</p> <p>A cedar, 20 ins. diam., bears N.68*E., 30 lks. dist.</p> <p>A cedar, 16 ins. diam., bears S.60*E., 15 lks. dist.</p> <p>A cedar, 24 ins. diam., bears S.60*W., 30 lks. dist.</p> <p>A red fir, 20 ins. diam., bears N.46*W., 88 lks. dist.</p> <p>Trees same as notes furnished except their growth.</p> <p>Set new cedar post, 36 ins. long, 10 ins. wide, 4 ins. thick, 20 ins. in ground, from which I run</p> <p>West, bet. secs. 1 and 12.</p> <p style="text-align: right;">Va.18*E.</p>	
38.00	Baker's Cabin, East 75 lks.	
38.25	Trail up river.	
40.00	Set maple post, 5 ins. diam., 50 ins. long, 24 ins. in ground, for the $\frac{1}{4}$ sec. cor. bet. secs. 1 and 12,	