

Meanders of North Fork Umpqua T. 26 S., R. 5 W

CHAINS	Courses	Chains	Remarks.
	N.84 *W.	22.00	In Section No. 20 (Cont).
	S.70 *W.	9.60	
	S.62 *W.	10.90	
	S.58 ³ / ₄ *W.	15.40	
	S.70 ¹ / ₂ *W.	2.98	To Meander post between Secs. 19 & 20.

	N.80 ¹ / ₂ *W.	12.00	In Section No. 19.
	S.82 *W.	5.70	
	S.57 ¹ / ₄ *W.	5.54	
	S.27 ¹ / ₄ *W.	3.20	
	S.32 ¹ / ₄ *E.	5.05	
	S.41 ¹ / ₂ *E.	11.32	Bank low. Timber, Alder, Ash, Maple.
	S.44 *E.	16.00	Undergrowth Willow, Ash.
	S.35 *E.	4.60	To Meander post between Secs. 19 & 20.

			In Section No. 20.
	S.24 ¹ / ₂ *E.	4.35	To Meander post between Secs. 20 & 29.

	South	0.20	In Section No. 29.
	S.20 *E.	3.01	
	South	5.74	
	S.30 *E.	4.38	
	S.20 *W.	1.92	To Meander post between Secs. 29 & 30.

	S.52 ³ / ₄ *W.	6.50	In Section No. 30.
	S.82 ¹ / ₂ *W.	4.82	Bank very high and steep. Timbered
	N.67 *W.	14.20	with Fir and Oak.
	N.72 ¹ / ₂ *W.	22.24	
	N.68 ³ / ₄ *W.	14.50	Bank low. Timber, Fir, Maple, Ash.
	N.80 *W.	8.80	
	S.85 *W.	7.00	Timber- Fir, Maple, Underg. Hazel, Willow.
	S.78 ¹ / ₂ *W.	11.68	To Meander post in West Boundary of Township.
