

Resurvey of 6th Stan. Par. S. through R. 1 W. 18725

CHAINS

Timber, fir, pine and hemlock.

Undergrowth, laurel.

Mountainous or heavily timbered land or land covered with dense undergrowth, 74.10 chs.

Note: This stan. cor. was destroyed and reestablished at a point 70.77 chs. W. of the stan. cor. for secs. 31 and 32. See notes of the resurvey of the West Bdy. of T. 27 S., R. 1 W.

Resurvey of a Portion of the W. Bdy. of T. 27 S., R. 1 W.
Same Deputy and Contract.

June 20, 1902.

Preliminary to commencing the subdivision of this Township, I run N. on a blank line on the W. bdy. of sec. 31 .

At 40.00 chs. I find the $\frac{1}{4}$ sec. cor. , E. 30 lks. dist. and at 80.00 chs. the cor. of secs. 25, 30, 31 and 36, E. 78 lks. dist. Therefore I continue my line N. and find no part of the W. bdy. in alinement nor measurement and that many of the corners are nearly obliterated.

At 5 miles and 8.90 chs. intersect E. and W. line 3.33 chs. W. of the cor. of secs. 1, 6, 7 and 12 and as these Tps., 27 S., Rs. 1 and 2 W. have not been subdivided with the exception of the north tier of secs. in T. 27 S., R. 2 W., I survey the range line between them S. of this tier as follows:

The old cor. of secs. 1, 6, 7 and 12 is a post greatly decayed and the marks are nearly obliterated. I destroy the post and in its place set a basalt stone, 18x10x6 ins., 12 ins. in the ground for cor. of secs. 1, 6, 7 and 12, marked with 1 notch on N. and 5 notches on S. edges, witnessed as described by the Surveyor General.

Thence I run

S. on a random line , along the W. bdy. of T. 27 S., R. 1 W., setting temp. $\frac{1}{4}$ sec. and sec. cors. at intervals