

-/-
County Surveyor's Record, Douglas County, Oregon

5219

Exterior Lines of Tp. 28 S., R. 7 W.
as surveyed by Nathaniel Ford, Deputy Surveyor,
under Contract No. 44, dated May 30, 1854.

CHAINS		September 4, 1854.
	Commenced at the NE. corner on the line dividing Ranges 6 and 7 West, and run the 6th Standard Parallel West, through Range 7.	
	West, on the North boundary of Sec. 1, Va. 18*25'E.	
3.00	Entered Looking Glass prairie, bears N.65*E. and S.33*E.	-30
7.44	To closing cor.	
40.00	Set $\frac{1}{4}$ Sec. post, made a trench and drove a charred stake in the center, as per instructions.	level
47.44	Set $\frac{1}{4}$ Sec. post, made a trench and drove a charred stake 12 ins. long, in the center, as per instructions.	level
80.00	Set a post, cor. of Secs. 1 and 2; made a trench and drove a charred stake, 12 ins. long in the center, as per instructions, for Standard cor.	level
	West, on the North boundary of Sec. 2. Va. 18*20'E.	
7.44	Set a post, cor. of Secs. 35 and 36, made a trench and drove a charred stake in the center, as per instructions for closing cor.	level
	Va. 18*20'E.	
40.00	Set $\frac{1}{4}$ Sec. post, made a trench, drove a charred stake 12 ins. long at the center, as per instructions.	level
47.44	Set $\frac{1}{4}$ Sec. post, made a trench and drove a charred stake 12 ins. long, in the center, as per instructions.	level
80.00	Set a post, cor. of Secs. 2 and 3, made a trench and drove a charred stake 12 ins. long, in the center, as per instructions for Standard cor.	
	First rate soil. Level prairie.	