

Subdivisions of T. 28 S., R. 8 W.

CHAINS

most of the timber.

West, on random line, between Secs. 7 and 18.

40.00 Temporary $\frac{1}{4}$ Sec. post.

79.60 Intersect West boundary at Sec. post.

East on true line, between Secs. 7 and 18.

Va.20*30'E.

39.80 Set post, 4 ft. long, 4 ins. diam., 1 ft. in the ground,
for $\frac{1}{4}$ Sec. post, from which

A Fir, 40 ins. diam., bears S.70*W., 17 lks. dist.

A Yew, 8 ins. diam., bears S.25*W., 65 lks. dist.

This cor. is on precipitous slope, facing South.

70.00 Summit of spur.

79.60 Intersect post at cor. of Secs. 7, 8, 17 and 18.

Land, broken and mountainous.

Soil, third rate.

Timber, good; Fir, Cedar, Hemlock and Yew.

August 5, 1875.

The portion of this Township included in the foregoing survey, is on or near the summit of the "Coast Range" mountains. Very little of it is at all valuable, except for the timber (mostly Fir), which covers the hillsides.

The aspect of the country is broken and precipitous, and only a great demand for lumber will render this land valuable for its timber.

Subdivision of T. 28 S., R.8 W.
as surveyed by George S. Pershin, Deputy Surveyor,
under Contract No. 238, dated July 13, 1875.

North, on random line, between Secs. 4 and 5.

Va.19*40'E.