

Subdivisions of T. 28 S., R. 8 W.

CHAINS	<p>Land, Surface some broken.</p> <p>Soil, third rate.</p> <p>Good timber, Fir, Hemlock, Cedar and Yew, some Vine Maple and Laurel undergrowth.</p> <p style="text-align: right;">October 16, 1875.</p>	
	<p>East, on a random line, between Sec. 5 and 8,</p> <p style="text-align: right;">Va.19*40'E.</p>	
40.00	Set post, for temporary $\frac{1}{4}$ Sec. cor.	
80.86	<p>Intersected North and South line, 92 lks. South of cor. to Secs. 4, 5, 8 and 9, from which cor. I run S.89*21'W. on a true line, between Secs. 5 and 8,</p> <p style="text-align: right;">Va.19*40'E.</p>	
7.50	Spring branch, course SE.	
28.00	Steep, rocky ascent,	+200
40.43	<p>Set Fir post for $\frac{1}{4}$ Sec. cor. on top of bluff, from which</p> <p>A Hemlock, 16 ins. diam., bears N.45*E., 30 lks. dist.</p> <p>A Chestnut, 8 ins. diam., bears S.43*W., 78 lks. dist.</p>	+250
80.86	<p>The cor. to Sec. 5, 6, 7 and 8</p> <p>Land: surface East $\frac{1}{2}$ mile, very broken and precipitous; West $\frac{1}{2}$ mile, rolling.</p> <p>Soil, part third rate; large part worthless.</p> <p>Timber, East $\frac{1}{2}$ mile, very scattering; West $\frac{1}{2}$ mile, good. Fir, Hemlock, Cedar and Yew. Some Vine Maple and Laurel undergrowth.</p>	-150
	<p>West, on a random line, between Secs. 6 and 7,</p> <p style="text-align: right;">Va.19*40'E.</p>	
40.00	Set post, for temporary $\frac{1}{4}$ Sec. cor.	
79.38	<p>Intersected West boundary, 42 lks. South of cor. to Sec. 6 and 7, from which cor. I run S.89*42'E. on a true line, between Sec. 6 and 7,</p> <p style="text-align: right;">Va.19*40'E.</p>	
39.38	Set Fir post for $\frac{1}{4}$ Sec. cor., from which	