

## Subdivision of T. 28 S., R. 8 W.

## CHAINS

A Fir, 32 ins. diam., bears N.8\*E., 32 lks. dist.  
 A Chestnut, 8 ins. diam., bears S.43\*W., 30 lks.  
 dist.

48.50 Spring branch, course SW.

79.38 The cor. to Sec. 5, 6, 7 and 8.

Land: Surface, undulating.

Soil; third rate.

Good timber: Fir, Hemlock, Cedar and Yew. Some Laurel  
 and Vine Maple undergrowth.

North, on a random line, between Secs. 5 and 6,

Va.19\*40'E.

40.00 Set post, for temporary  $\frac{1}{4}$  Sec. cor.

80.78 Intersected North boundary, 68 lks. West of cor. to Sec.  
 5 and 6, from which cor. I run

S.29'W. on a true line, between Secs. 5 and 6,

Va.19\*30'E.

10.75 Brook, 5 lks. wide, course West, -150

16.50 Spring branch, course NW. -30

30.75 Spring branch, from South course NW.

38.25 Spring branch, from SW. course North, +60

40.78 Set Yew post for  $\frac{1}{4}$  Sec. cor., from which +40

A Cedar, 10 ins. diam., bears East, 31 lks. dist.

A Yew, 6 ins. diam., bears S.50\*W, 16 lks. dist.

44.00 Spring branch, course NW. +50

58.00 Spring branch, course NW. +60

80.78 The cor. to Secs. 5, 6, 7 and 8, +150

Land: Surface, much broken.

Soil: third rate.

Good timber, Fir, Hemlock, Cedar, Yew and Chestnut; a  
 very little Vine Maple and Laurel undergrowth.

Oct. 17, 1875.

## General Description:

This part of this Township lies mostly on the summit of