

## Resurvey of Sec. 33, T. 27.S., R. 7 W.

CHAINS	Thence from the $\frac{1}{2}$ sec. cor. S.0°15'E., bet. secs. 32 and 33.
1.80	Looking Glass-Reston Road, bears NW. and SE.
4.55	Looking Glass Creek, 30 lks. wide, course E.; ascend 492 ft. on NE. slope.
35.40	Top of spur, slopes N.20°W.; continue ascent 12 ft. on NW. slope.
36.67	Intersect the original N. bdy. of sec. 5. <sup>COR.</sup> / <u>established</u> by Ford for cor. of secs. 32 and 33, now angle point, bears S.88°20'E., 2.52 chs. dist.
40.13	Intersect the Hathorn cor. of secs. 32 and 33, heretofore described.  Land, rolling and mountainous. Soil, clay loam 2nd rate. Timber, fir, oak, pine, and laurel. Undergrowth, hazel, vinemaple, oak, laurel, and pine.
7.43	East, bet. resurveyed secs. 5 and 33. The cor. established by Hathorn for cor. of secs. 4 and 5 now restored as angle point, heretofore described, Thence N.89°39'E.
2.64	Intersect the resurvey NE. cor. of sec. 5, on W. bdy. of original sec. 4, heretofore described. Thence N.4°52'W., bet. resurvey sec. 33 and original sec. 4.
3.30	Intersect Ford's original cor. of secs. 4 and 5, restored as NW. cor. of sec. 4 only, hereafter described. Thence S.87°38'E., bet. resurvey sec. 33 and original sec. 4.
29.96	Intersect meridional center subdivision line of original sec. 33 and angle point No.9 of resurvey sec.33, here- after described. Thence S.0°04'W., on center meridional subdivision line of original sec. 33, through overlap of sec. 4.