

Subdivisions, T. 28 S., R. 7 W.

CHAINS

county surveyor at the intersection of fences bearing N., S., and E. The old bearing trees marked by Ford are plainly marked, but the record of them is erroneous and cannot be made to harmonize with the cor. position.

Along side the cor. post

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

$\frac{1}{4}$ S30
S31
1924

from which (the original bearing trees)

A black oak, 26 ins. diam., bears S. 62*E., 31 lks. dist., (not S.23*E., 99 lks.)

A black oak, 36 ins. diam., bears N. 9*W., 126 lks. dist. (not N.40*E., 76 lks.)

New bearing trees:

A black oak, 40 ins. diam., bears N.41*E., 105 lks. dist., marked $\frac{1}{4}$ S 30 B T.

A black oak, 30 ins. diam., bears S.21*W., 49 lks. dist., marked $\frac{1}{4}$ S 31 B T.

Thence from the $\frac{1}{4}$ sec. cor.

N.88*23'W., bet. secs. 30 and 31.

12.17 Intersect the E. bdy. of Tract No. 61. S.0*29'W., 15.03 chas. from Cor.No. 1, hereafter described.

36.45 Dry Draw, course SW.

37.25 Dry draw, course SE.

38.40 Fence, bears N. and S.

44.90 Newland's house bears South, 150 lks. dist.

45.85 Fence, bears NW. and S.

46.35 Road, bears NW. and S.

46.85 Fence, bears NW. and S.

47.00 Ditch, Bears NW. and SE.

48.23 Intersect Hathorn's E. bdy. of T. 28 S., R. 8 W., at the resurveyed cor. of secs. 30 and 31, hereafter described.

From this cor. the original cor. of secs. 25, 30,31, and