

Re-Survey of Subdivision Lines of T 29 S. R. 6 W.

CHAINS	
	At the cor. of secs. 19, 20, 29 and 30.
	The line bet. secs. 29 and 30 being out of limits with the W. bdy. of sec. 30, from the above described corner
	I run
	South, 89°35'W. on a random line bet. secs. 19 and 30.
40.00	The $\frac{1}{4}$ sec. cor. is not found after careful search. Set temp $\frac{1}{4}$ sec. cor.
83.00	Intersect W. bdy. of the Tp. 42 lks. North of the cor. of secs. 19, 24, 25 and 30, which I re-established July 28, 1905.
	Thence I run
	N.89°18'E. on a true line bet. secs. 19 and 30.
	Along creek bottom through heavy timber and dense undergrowth.
2.00	Blazed trail bears N. and S.
	Thence along N. slope of mountain.
22.34	Picket fence bears N. and S. Enter G. H. Baker's field,
24.50	Picket fence bears N. and S. Leave field.
25.00	Creek, 2 lks. wide, course N.
	Ascend W. slope.
43.00	Re-establish the $\frac{1}{4}$ sec. cor. as follows:
	Set an ironstone 12x8x6 ins. 8 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face, from which:
	A Laurel, 12 ins. diam., bears N. 72°E., 26 lks. dist., marked $\frac{1}{4}$ S 19 B T.
	A Laurel, 30 ins. diam., bears S. 3°E., 33 lks. dist., marked $\frac{1}{4}$ S 30 B T.
47.00	Summit of divide bet. East and West Forks of Rice creek bears N. and S.
	Descend E. slope.
69.00	East Fork of Rice creek, 4 lks. wide, course NW.
	Ascend W. slope.
73.50	Wagon road bears N. and S.