

## Supplemental Notes, T. 30 S., R. 1 W.

CHAINS

Distance from 1/4 corner on S. Bdy. of sec. 5 to corner of secs. 4 and 5, 40.00 chs. Distance from corner of secs. 4 and 5 to 1/4 sec. corner on S. bdy. sec. 4, 40.00 chs. Distance from 1/4 sec. corner bet. secs. 8 and 9 to CC of secs. 8 and 9 is 42.00 chs.

Resurvey of Subdivisions, T. 30 S., R. 1 W.  
Same Deputy and Contract.

I commence at the corner of secs. 7, 8, 17 and 18, which I find nearly obliterated. The old corner which was a post has disappeared. The laurel described as bearing tree in sec. 7 in dead though still standing, with some of the marks yet legible. The other bearing trees have fallen and decayed.

I destroy the old marks and re-establish the corner in its original position as follows:

Set an ironstone 15x10x8 ins. 10 ins. in the ground for corner of secs. 7, 8, 17 and 18, marked with 4 notches on S. and 5 notches on E. edge; from which

A red fir, 9 ins. diam., bears N.17°E., 36 lks. dist., marked T 30 S R 1 W S 8 B T.

A red fir, 10 ins. diam., bears S.24°E., 35 lks. dist., marked T 30 S R 1 W S 17 B T.

A red fir, 12 ins. diam., bears S.4°W., 23 lks. dist., marked T 30 S R 1 W S 18 B T.

A red fir, 12 ins. diam., bears N.86°W., 23 lks. dist., marked T 30 S R 1 W S 7 B T.

Thence, I run

S.89°28'E. on a random line bet. secs. 8 and 17.

40.00 The 1/4 sec. corner is not found after careful search. Set temp. 1/4 sec. corner.

81.10 Intersect corner of secs. 8, 9, 16 and 17, which is partially obliterated. The old corner which was a post has disappeared, and three of the bearing trees are dead