

Resurvey of Subdivisions, T. 30 S., R. 1 W.

CHAINS	
	N.0*35'W. bet. secs. 1 and 2.
20.00	Summit of ridge bears E. and W. Desc. N. slope.
40.60	Intersect corner of secs. 1, 2, 35 and 36, on N. bdy. of the Tp., which is a post, greatly decayed, marked and witnessed as described by the surveyor general.
	The C. of this line is N.0*35'W. and the length is 40.60 chs.
	Land, mountainous.
	Soil, loam and stony, second and third rate.
	Timber, red and white fir, sugar pine, cedar, hemlock; undergrowth, arrowwood, hazel, vine maple, fir.
	Mountainous or heavily timbered land or land covered with dense undergrowth, 81.20 chs.
	The line bet. secs. 4 and 5 being out of limits with the reported length of the line bet. secs. 5 and 6, I commence at the corner of secs. 5, 6, 7 and 8, previously described,
	Thence, I run
	N.0*4'W. bet. secs. 5 and 6.
	Over mountainous land through heavy timber and dense undergrowth.
	Asc. SE. slope.
17.00	Top of bench on W. slope.
	Thence along W. slope.
35.66	Creek, 2 lks. wide, C. SE.
39.22	Settlers' trail bears E. and W.
40.75	Intersect the $\frac{1}{2}$ sec. corner, which is nearly obliterated. The old corner, which was a post, has disappeared and the chinquapin, described as bearing tree in sec. 5 has fallen and decayed. I destroy the old marks and reestablish the corner in its original position as follows: