

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T.30 S., R.4 W.

<p>CHAINS 42.05</p>	<p>1/4 Sec. Cor. The post set for this corner is gone, fire having been through here, probably 20 years ago. The bearing tree in Sec. 19, a B. oak, is lying down, showing the axe marks, but no letter distinctly, simply surveyor marks. Nothing remains of the W. oak in Sec. 30. I restore this corner by setting a basalt rock 15x8x7 ins., 10 ins. in the ground, marked 1/4 on N. face, from which</p> <p>A laurel, 6 ins. diam., bears South 7 lks. dist., marked 1/4 S B T.</p> <p>A fir, 12 ins. diam., bears N.80*E., 17 lks. dist., marked 1/4 S B T.,</p>	<p>+200</p>
	<p>Thence S.89*01'E., on true line, between Secs. 19 and 30. Var. 18*40'E.</p>	
	<p>Ascending through heavy underbrush.</p>	
<p>.10</p>	<p>Same ravine, course N.60*W.</p>	
<p>4.00</p>	<p>Same ravine, course S.60*W.</p>	
<p>16.50</p>	<p>Top of ridge; trail, course N. and E. Leave heavy underbrush, enter oak openings, begin descent.</p>	
<p>31.50</p>	<p>A ravine, course S., descend along S. hillside.</p>	<p>-120</p>
<p>39.10</p>	<p>The Cor. to Secs. 19, 20, 29 and 30. Land, mountainous. Soil, coarse gravel, 3d rate. Timber, fir, oak, laurel and pine. Undergrowth, hazel and young firs, oaks and laurels.</p>	
	<p>May 25, 1889.</p>	
	<p>Var. 18*35'E,</p>	
	<p>North, on a random line between Secs. 19 and 20.</p>	
<p>36.85</p>	<p>1/4 Sec. Cor. bears East 47 lks.</p>	
<p>75.90</p>	<p>Intersect North Bdy. of Sec. 19, 87 lks. West of Cor. to Secs 17, 18, 19 and 20. The post set for this corner is gone, but all the bearing trees are standing. I restore by setting an oak post, 4 ft. long, 4 ins.</p>	