

Retracements of Subdivisional lines of T. 30 S., R. 5 W.

CHAINS

Mountainous, land. 79.76 chs.

May 1, 1897

Corrections to Subdivisions of T. 30 S., R. 5 W.

Same Deputy and Contract.

Line bet. secs. 1 and 2. add

Pits impracticable.

Line bet. secs. 2 and 3. add

Pits impracticable.

Line bet. 10 and 11.

The post for cor. of secs. 10, 11, 14 and 15, being gone, but the old bearing trees remaining I re-establish.

Line bet. secs. 3 & 4.

All marks on old post and bearing trees, referring to the new work were effaced or corrected.

Line bet. secs. 4 & 9.

The post for cor. of secs. 4, 5, 8 & 9 being gone, but the old bearing trees remaining, I re-establish the cor. by setting a maple post, 3 ft. long, 5 ins. sq. 24 ins. in the ground, marked T 30 S S 4 on NE., R 5 W S 9 on SE., S 8 on SW., and S 5 on NW faces with 5 notches on E. edges; from which,

An alder, 15 ins. diam., bears N.20°E, 150 lks. dist. marked T 30 S R 5 W S 4 B T.

A B oak, 8 ins. diam., bears N.35°W, 233 lks. dist. marked T 30 S R 5 W S 5 B T.

A W oak, 6 ins. diam., bears S.41½°W, 55 lks. dist. marked T 30 S R 5 W S 8 B T.

A W oak, 6 ins. diam., bears S.11-3/4°E, 93 lks. dist. marked T 30 S R 5 W S 9 B T.

Oscar F. Thiel

U. S. Deputy Surveyor.

Old bearing trees

New bearing trees