

Retracement of Portion of West Boundary  
of T. 31 S., R. 1 W.

CHAINS

from which

A fir, 18 ins. diam., bears S.89 $\frac{1}{2}$ \*E., 138 lks. dist.,  
mkd. T 31 S R 1 W S 30 B T. (Old B T.)

The old bearing trees in secs. 19, 24, and 25 are  
dead and down.

A cedar, 22 ins. diam., bears N.65\*E., 83 lks. dist.,  
mkd. T 31 S R 1 W S 19 B T. (New B T.)

A fir, 5 ins. diam., bears S.50\*W., 45 lks. dist.,  
mkd. T 31 S R 2 W S 25 B T. (New B T.)

A fir, 5 ins. diam., bears N.75\*W., 14 lks. dist.,  
mkd. T 31 S R 2 W S 24 B T. (New B T.)

The bearing and length of the south half mile is North,  
40.46 chs., and of the north half mile is N.0\*17'E.,  
40.82 chs.

Land, mountainous.

Soil, 3rd. rate.

Timber, fir and cedar.

Undergrowth, vine maple.

Retracement of Portion of Subdivisional Lines  
in T. 31 S., R. 1 W.

From the cor. of secs. 19, 24, 25, and 30, on W. bdy. of  
the Tp. hereinbefore described.

S.89\*47'E., retracing bet. secs. 19 and 30.

39.20 After diligent search, find no evidence of the 1/4 sec. cor.

80.13 Fall 142 lks. S. of the cor. of secs. 19, 20, 29 and 30.

The bearing and length of this mile is S.89\*12'W., 80.14  
chs., proportional length of the east half mile is  
40.47 chs., and of the west half mile is 39.67 chs.

-----  
The cor. of secs. 19, 20, 29 and 30 is a badly decayed  
fir post, with marks still legible.

In place of the decayed post