

## Subdivisions of T. 31 S., R. 5 W.

## CHAINS

- 33.50 Top of spur, c SW. and NE.
- 40.00 Set temp.  $\frac{1}{4}$  sec. cor. Descend.
- 50.00 Ascend along steep N. slope.
- 67.00 Top of spur, c N. Descend.
- 85.60 Intersect N. and S. line, 23 lks. South of cor. to secs.  
8, 9, 16 and 17.
- Thence, I run  
S.89°50'W., on a true line between secs. 17 and 8, with  
same var.
- 40.00 Set a fir post, 3 ft. long, 3 ins. square, 18 ins. in ground,  
for the  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S on N. face, from which  
A yew, 7 ins. diam., bears S.45°W., 19 lks. dist.  
Marked  $\frac{1}{4}$  S B T.  
A fir, 13 ins. diam., bears N.17°W., 64 lks. dist.  
Marked  $\frac{1}{4}$  S B T.
- 85.60 To cor. to secs. 7, 8, 17 and 18.  
Land, mountainous and broken.  
Soil, rocky, third and fourth rates.  
Timber, dense forest of fir, cedar, yew, pine and laurel.  
Thick undergrowth of same kinds of wood with live oak,  
arrow-wood, hazel, and maple.

## General Description

This township is all mountainous and densely timbered except a narrow bottom along Canyon Creek, which, although level, is also heavily timbered. The soil is generally poor and the surface covered with rocks makes the lands worthless for agricultural purposes.

The stage road, "the Canyon Road", owned and controlled by a corporation, extends through the entire East tier of sections.