

WEST BOUNDARY OF T. 31 S., R. 9 W.

CHAINS

undergrowth. 71.71 chains.

April 26th, 1901.

GENERAL DESCRIPTION

This township is rough, mountainous, and in many places rocky and broken.

It is well watered, well timbered, and is said to contain much mineral wealth. Only a small portion of the township is fit for cultivation, viz: a few small vallies and benches.

There are several locations of lands in the township for agricultural or mineral purposes. The township lies wholly within the R. R. reserves and they should be subdivided.

Wm. H. Byars,
U.S. Deputy Surveyor.

Subdivisions of T. 31 S., R. 9 W.
Same Deputy and Contract.

I commence at the corner of Secs. 35 and 36 on the South boundary of the township, the corner established by me April 22nd, 1901.

Thence I run

N.0*01'W bet. Secs. 35 and 36.

Steep rocky descent.

3.00 Babe's Creek, 40 lks. wide, course NE. 100

Ascend rocky mountain.

12.00 Top of rocky spur, course E. 200

20.00 Steep descent.

26.00 West fork 150 lks. wide, course E. 250

28.00 Steep ascent.

40.00 Set a Fir post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for the 1/4 Sec. cor. marked S 36 on E and 300