

Retracement-Reestablishment of East Bdy. of T.32 S., R.4 W.

CHAINS	
	A Yellow Pine, 5 ins. diam., bears N.79*W., 257 lks. dist., marked $\frac{1}{4}$ S 36 B T.
	I destroy the marks on the old bearing tree, referring to Sec. 31.
	The true course and distance of this line is N.0*19'W., 59.81 chs.
	I continue retracement of my line North from the $\frac{1}{4}$ Sec. cor., counting distance from Sec. cor.
61.00	Ravine, course SE.; ascend SE. slope.
65.80	Spur, slopes East; along East slope.
66.50	Enter heavy timber, bears NE. and SW.
75.00	Leave heavy timber, bears East and West; ascend SE. slope through low Buck Horn, Manzanita and live Oak.
83.80	Spur, slopes East; descend NE. slope.
85.00	Enter heavy timber, bears East and West.
97.90	Creek, 3 lks. wide, course East; ascend South slope.
99.53	Fall 30 lks. West of the cor. of Secs. 25, 30, 31 and 36, which is a stone, firmly set, marked and witnessed as described by the Surveyor General and which I now change to refer to Secs. 25 and 36 only, and destroy the marks on the old bearing trees in Secs. 30 and 31.
	The true course and distance of this line from the $\frac{1}{4}$ Sec. cor. is N.0*26'E., 39.72 chs.
	Land, mountainous.
	Soil to 26.00 chs., stony, clay loam; third rate; to 99.53 chs., rocky, unfit for cultivation.
	Timber, Fir, Madrona, Chinquapin, Pine and Cedar.
	Undergrowth, Manzanita, live Oak, Chinquapin and Fir.
	Sky overcast during afternoon, meridian observation impossible.
	September 13, 1913.