

Retracement-Reestablishment of East Bdy. of T. 32 S., R. 4 W.

CHAINS

General Description.

The land along these lines is rough and mountainous; the soil is third and fourth rate, well watered.

There is a good stand of timber along these lines.

Retracement and Reestablishment of Subdivision
Lines of T. 32 S., R. 3 W. as surveyed by Fred Mensch,
Deputy Surveyor, August 20, 1912.

Methods of Procedure.

Discrepancies developed in the closings of the sections, when completing the subdivision of this Tp., made it necessary to retrace all the old lines bounding the unsurveyed portion of the Tp. In this record the lines are given in order, from East to West, and from South to North, and not in the order in which they were run.

At the cor. of Secs. 13, 14, 23 and 24.

Thence I retrace

East, on South Bdy. of Sec. 13; at 40.16 chs. I intersect the $\frac{1}{4}$ Sec. cor.

Commencing again at the $\frac{1}{4}$ Sec. cor., I continue the retracement East, and at 56.97 chs., intersect the closing cor. of Secs. 13 and 24, on the East Fdy., of the Tp., heretofore described.

Thence I run

West, on South Fdy. Sec. 13.

Descend West slope, through dense timber and undergrowth.

22.40 Trail, bears North and South.

23.20 Cow Creek, 20 lks. wide, course North. Ascend East slope.

55.50 Spur, slopes SE. Ascend SE. slope.

56.97 Intersect the $\frac{1}{4}$ Sec. cor., which is a stone, firmly set, marked and witnessed as described by the Surveyor General, and which I now change to refer to Sec. 13 only,