

Subdivisions, T. 32 S., R. 4 W.

CHAINS

Timber, Fir, Cedar, Hemlock, and Madrona.

Dense undergrowth of mountain-balm, Ocean-spray, Hazel and Salal-berry.

Land, mountainous, heavily timbered or covered with dense undergrowth. 35.04 chs.

I know the measurements of 35.04 on S. half of line bet. secs. 2 and 3 to be correct from the following procedure:

On Aug. 15, 1897, I retraced the E. bdy. of sec. 2 for the purpose of locating corner of secs. 1, 2, 11 and 12. From the established corner of secs. 1, 2, 35 and 36, which is a post 24 ins. above ground, 4 ins. sq., marked and witnessed as described by the surveyor general, I ran South on a blank line, bet. secs. 1 and 2.

35.77

To a point, 3 lks. W. of $\frac{1}{4}$ sec. corner; post destroyed; bearing trees standing, from which I reestablished this $\frac{1}{4}$ sec. corner as follows:

Set a Yew post, 4 ins. sq., 3 ft. long, 24 ins. in the ground for $\frac{1}{4}$ sec. corner, marked $\frac{1}{4}$ S. on W. face, from which,

A Yew, 6 ins. diam., bears S.50*E., 37 lks. dist., marked $\frac{1}{4}$ S., B. T.

A Fir, 5 ins. diam., bears S.75*W., 9 lks. dist., marked $\frac{1}{4}$ S., B. T.

75.22

To a point, 5 lks. W. of the corner of secs. 1, 2, 11 and 12, which I reestablished to refer to secs. 2 and 11.

From the corner of secs. 3, 4, 9 and 10, which is a post 24 ins. above ground, marked and witnessed as described by the surveyor general, I run East on a true line, bet. secs. 3 and 10.

Desc.