

## Subdivisions, T. 32 S., R. 4 W.

## CHAINS

39.18 To a point, 55 lks. N. of the  $\frac{1}{4}$  sec. corner, which is a post badly decayed; and which I reestablish at same point as follows:

Set a basalt stone, 12 x 10 x 8 ins., 8 ins. in the ground for  $\frac{1}{4}$  sec. corner, marked  $\frac{1}{4}$  on N. face; from which

A Fir, 16 ins. diam., bears N.52\*W., 25 lks. dist., marked  $\frac{1}{4}$  S B T.

A Fir, 36 ins. diam., bears S.80\*E., 27 lks. dist., marked  $\frac{1}{4}$  S B T.

Therefore, this line bears

South, 89\*43'W.

From this  $\frac{1}{4}$  sec. corner, I run

North, 89\*30'W. on a blank line.

39.00 To a point 63 lks. N. of the corner of secs. 5, 6, 7 and 8, which is a post 4 ins. sq., 24 ins. above ground, marked and witnessed as described by the surveyor general.

Therefore, this line bears

South, 89\*35'W.

---

Having found all lines which I have closed upon, thus far, in this township irregular in measurement or alinement, I retrace the east bdys. of secs. 7 and 18 while in this vicinity, to preclude the necessity of retracement later, at less opportune time.

Thence, I run

South, on a blank line, on the E. bdy. of sec. 7.

40.06 To a point, 18 lks. W. of the  $\frac{1}{4}$  sec. corner, which I find to be entirely destroyed except the bearing tree in sec. 8, from which I reestablish this corner as follows: