

Subdivisional Lines of T. 32 S., R. 5 W.,

CHAINS  
78.10

The cor. of secs. 4, 5, 8 and 9; 250 ft. below top of mountain ridge.

Land mountainous, very rough.

Soil gravelly and rocky; 3rd and 4th rate.

Timber, fir, cedar, laurel, live oak.

Undergrowth, hazel, small firs, arrowwood.

Mountainous and heavily timbered Land 78.10 chs.

July 24, 1901.

---

At the cor. of secs. 7, 8, 17 and 18, which having disappeared, I reestablish by setting a granitestone 14x12x8 ins., 10 ins. in the ground, for cor. of secs. 7, 8, 17 and 18 marked with 4 notches on S. and 5 notches on E. edges, and witnessed as described by the surveyor general. Thence I run

N.89\*49'W. on a random line bet. secs. 7 and 18.

Descend mountain slope, covered heavily with timber,

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

84.45 Intersect the W. bdy. of Tp. 50 lks. S. of cor. of secs. 7, 18, 12 and 13, which is gone, and I replace it by setting a cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 7, 8, 12 and 13, marked T. 32 S. S. 7 on NE., R. 5 W. S. 18 on SE., S. 13 on SW., and R. 6 W. S. 12 on NW. faces, with 2 notches on N. and 4 notches on S. edges; from which

A Wh. fir, 14 ins. diam. bears N.43\*W., 30 lks.

Marked T. 32 S. R. 6 W. S. 12 B.T.

The other bearing trees as described by the surveyor general. Thence I run

S.89\*28'E. on true line bet secs. 7 and 18.

Begin steep ascent of slope of mountain spur, covered heavily with timber.

8.20 Top of spur, bears N. and S.; 100 ft. above cor., begin descent of E. and SE. slope, covered with a